



## RYOBI RECALLS CORDLESS DRILLS DUE TO FIRE HAZARD

Release #11-009

Firm's Recall Hotline: (800) 597-9624

CPSC Recall Hotline: (800) 638-2772

CPSC Media Contact: (301) 504-7908

WASHINGTON, D.C. - The U.S. Consumer Product Safety Commission, in cooperation with the firm named below, today announced a voluntary recall of the following consumer product. Consumers should stop using recalled products immediately unless otherwise instructed. It is illegal to resell or attempt to resell a recalled consumer product.

Name of Product: Ryobi Model HP 1802M Cordless Power Drills

Units: About 455,000

Importer: Ryobi Technologies Inc., of Anderson, S.C.

Hazard: The switch on the cordless drill can overheat, posing a fire and burn hazard to consumers.

Incidents/Injuries: Ryobi has received 47 reports of the drills overheating, smoking, melting or catching fire, including 12 reports of property damage to homes or vehicles. Two of the incidents involved minor burns from touching an overheated switch.

Description: The Ryobi Model HP 1802M cordless drill is powered by an 18 volt rechargeable NiCad battery. The drills are blue and black in color with "Ryobi" appearing in red and white on the left side. The model number can be found on a white label on the right side of the drill.

Sold at: Home Depot from January 2001 to July 2003 for about \$100.

Manufactured in: China

Remedy: Consumers should immediately stop using the recalled drill, remove the rechargeable battery and contact Ryobi to receive a free replacement drill.

To see this recall on CPSC's web site, including pictures of the recalled product, please go to:

<http://www.cpsc.gov/cpsc/pub/prerel/prhtml11/11009.html>



Distributed by the  
NYS Division of Homeland Security and Emergency Services

OFFICE OF  
**FIRE PREVENTION  
& CONTROL**

**phone** 518.474.6746  
**fax** 518.474.3240  
**email** fire@dos.state.ny.us