

```

<?xml version="1.0" standalone="yes"?>
<TRACS_IMPORT>
  <ALCOTEST_VALUES>
    <SERIAL>ARAH-0026</SERIAL>
    <IP_ADRESS>10.81.201.35</IP_ADRESS>
    <DATE>12/25/2019</DATE>
    <TIME>07:24PM</TIME>
  </ALCOTEST_VALUES>
  <CALCHECK_1>
    <CAL_MESSUNG_2_MESSUNG_ERROR>0</CAL_MESSUNG_2_MESSUNG_ERROR>
    <CAL_MESSUNG_2_IR_AAK_NULLWERT_1>0.00</CAL_MESSUNG_2
_IR_AAK_NULLWERT_1>
    <CAL_MESSUNG_2_IR_AAK_MESSWERT>0.10</CAL_MESSUNG_2
_IR_AAK_MESSWERT>
    <CAL_MESSUNG_2_EC_AAK_MESSWERT>0.09</CAL_MESSUNG_2
_EC_AAK_MESSWERT>
    <CAL_MESSUNG_2_IR_AAK_NULLWERT_2>0.00</CAL_MESSUNG_2
_IR_AAK_NULLWERT_2>
    <ID_BLANK_TIME_BEFORE_2>07:12:29PM
12/25/2019</ID_BLANK_TIME_BEFORE_2>
    <ID_TIME_START_BLOW_2>--:--:-- --/--/-----
</ID_TIME_START_BLOW_2>
    <ID_TIME_MEAS_2>07:13:06PM 12/25/2019</ID_TIME_MEAS_2>
    <ID_BLANK_TIME_AFTER_2>07:13:42PM
12/25/2019</ID_BLANK_TIME_AFTER_2>
  </CALCHECK_1>
  <SUBJECT_TEST>
    <PROB_MESSUNG_2_MESSUNG_ERROR>0</PROB_MESSUNG_2
_MESSUNG_ERROR>
    <PROB_MESSUNG_2_IR_AAK_NULLWERT_1>0.00</PROB_MESSUNG_2
_IR_AAK_NULLWERT_1>
    <PROB_MESSUNG_2_IR_AAK_MESSWERT>0.29</PROB_MESSUNG_2
_IR_AAK_MESSWERT>
    <PROB_MESSUNG_2_EC_AAK_MESSWERT>0.29</PROB_MESSUNG_2
_EC_AAK_MESSWERT>
    <PROB_MESSUNG_2_IR_AAK_NULLWERT_2>0.00</PROB_MESSUNG_2
_IR_AAK_NULLWERT_2>
    <PROB_MESSUNG_2_BLAS_FEHLVERSUCHE>2</PROB_MESSUNG_2
_BLAS_FEHLVERSUCHE>
    <PROB_MESSUNG_2_BLAS_VOLUMEN>3.1</PROB_MESSUNG_2
_BLAS_VOLUMEN>
    <PROB_MESSUNG_2_BLAS_ZEIT>11.5</PROB_MESSUNG_2_BLAS_ZEIT>
    <ID_BLANK_TIME_BEFORE_3>07:19:37PM 12/25/2019,07:14:50PM
12/25/2019,07:17:36PM 12/25/2019</ID_BLANK_TIME_BEFORE_3>
    <ID_TIME_START_BLOW_3>07:19:59PM 12/25/2019,07:15:50PM
12/25/2019,07:17:56PM 12/25/2019</ID_TIME_START_BLOW_3>
    <ID_TIME_END_BLOW_3>07:20:10PM 12/25/2019,07:15:59PM
12/25/2019,07:18:05PM 12/25/2019</ID_TIME_END_BLOW_3>
    <ID_TIME_MEAS_3>07:20:19PM 12/25/2019,07:16:09PM
12/25/2019,07:18:05PM 12/25/2019</ID_TIME_MEAS_3>
    <ID_BLANK_TIME_AFTER_3>07:21:51PM
12/25/2019</ID_BLANK_TIME_AFTER_3>

```

```

</SUBJECT_TEST>
<CALCHECK_2>
  <CAL_MESSUNG_3_MESSUNG_ERROR>0</CAL_MESSUNG_3_MESSUNG_ERROR>
  <CAL_MESSUNG_3_IR_AAK_NULLWERT_1>0.00</CAL_MESSUNG_3
_IR_AAK_NULLWERT_1>
  <CAL_MESSUNG_3_IR_AAK_MESSWERT>0.09</CAL_MESSUNG_3
_IR_AAK_MESSWERT>
  <CAL_MESSUNG_3_EC_AAK_MESSWERT>0.09</CAL_MESSUNG_3
_EC_AAK_MESSWERT>
  <CAL_MESSUNG_3_IR_AAK_NULLWERT_2>0.00</CAL_MESSUNG_3
_IR_AAK_NULLWERT_2>
  <ID_BLANK_TIME_BEFORE_4>07:21:51PM
12/25/2019</ID_BLANK_TIME_BEFORE_4>
  <ID_TIME_START_BLOW_4>--:--:-- --/--/-----
</ID_TIME_START_BLOW_4>
  <ID_TIME_MEAS_4>07:21:52PM 12/25/2019</ID_TIME_MEAS_4>
  <ID_BLANK_TIME_AFTER_4>07:22:29PM
12/25/2019</ID_BLANK_TIME_AFTER_4>
</CALCHECK_2>
<GENERAL_DATA>
  <ID_SERIAL_NO>ARAH-0026</ID_SERIAL_NO>
  <ID_SW_VERSION> 8321288 1.12.2</ID_SW_VERSION>
  <ID_START_TIME>07:01:19PM 12/25/2019</ID_START_TIME>
  <ID_END_TIME>07:23:23PM 12/25/2019</ID_END_TIME>
  <ID_LAST_CAL_DATE>05/13/2019</ID_LAST_CAL_DATE>
  <ID_AAK_ENDRESULT> 0.29 %BAC</ID_AAK_ENDRESULT>
  <ID_TEST_COUNTER>507</ID_TEST_COUNTER>
  <ID_MEAS_PROC>1</ID_MEAS_PROC>
  <ID_CALIBRATION_COUNTER>101</ID_CALIBRATION_COUNTER>
  <ID_ERROR_PROTOKOLL>0</ID_ERROR_PROTOKOLL>
  <ID_TEST_GAS_TYPE>2</ID_TEST_GAS_TYPE>
  <ID_TEST_GAS_INLET>1</ID_TEST_GAS_INLET>
  <ID_TEST_GAS_CONC>25.00</ID_TEST_GAS_CONC>
  <ID_TEST_CFG_SENSOR>0</ID_TEST_CFG_SENSOR>
  <ID_DATA_INPUT_ON_OFF>1</ID_DATA_INPUT_ON_OFF>
  <ID_IR_AVERAGE>21490</ID_IR_AVERAGE>
  <ID_EC_SENSOR_OFFSET>113</ID_EC_SENSOR_OFFSET>
  <ID_HOSE_TEMP>47.0</ID_HOSE_TEMP>
  <ID_IR_SENSOR_TEMP>45.3</ID_IR_SENSOR_TEMP>
  <ID_INTERNAL_DEVICE_TEMP>37.8</ID_INTERNAL_DEVICE_TEMP>
  <ID_12V_VOLTAGE>12.3</ID_12V_VOLTAGE>
  <ID_3V_BACKUP_VOLTAGE>3.3</ID_3V_BACKUP_VOLTAGE>
  <ID_MS_SW_CRC>0x6581</ID_MS_SW_CRC>
  <ID_PRESSURE_DRY_GAS>0</ID_PRESSURE_DRY_GAS>
  <ID_DRY_GAS_LOT_NO>727773</ID_DRY_GAS_LOT_NO>
  <ID_DRY_GAS_EXP_DATA>03/02/2020</ID_DRY_GAS_EXP_DATA>
</GENERAL_DATA>
<INPUT_VALUES>
  <UF_CASE_NUMBER>9342888</UF_CASE_NUMBER>
  <ZERO_TOLERANCE_CASE>NO</ZERO_TOLERANCE_CASE>
  <TROOP>T</TROOP>
  <STATION>SYRACUSE</STATION>

```

<ARREST_DATE>12/25/2019</ARREST_DATE>
<ARREST_TIME>06:33PM</ARREST_TIME>
<ARRESTING_MEM_LAST>Fusco</ARRESTING_MEM_LAST>
<ARRESTING_MEM_FIRST>Travis</ARRESTING_MEM_FIRST>
<ARRESTING_MEM_MI>J</ARRESTING_MEM_MI>
<ARRESTING_MEM_SHIELD>400</ARRESTING_MEM_SHIELD>
<SUBJECT_LAST_NAME>Joseph</SUBJECT_LAST_NAME>
<SUBJECT_FIRST_NAME>James</SUBJECT_FIRST_NAME>
<SUBJECT_MI>--</SUBJECT_MI>
<SUBJECT_DOB>03/13/1976</SUBJECT_DOB>
<SUBJECT_AGE>43</SUBJECT_AGE>
<SUBJECT_GENDER>MALE</SUBJECT_GENDER>
<OPERATOR_LAST_NAME>Fusco</OPERATOR_LAST_NAME>
<OPERATOR_FIRST_NAME>Travis</OPERATOR_FIRST_NAME>
<OPERATOR_MI>J</OPERATOR_MI>
<OPERATOR_SHIELD_NO>400</OPERATOR_SHIELD_NO>
<OPERATOR_PERMIT_NO>46353</OPERATOR_PERMIT_NO>
<OPERATOR_PERMIT_EXP>11/17/2021</OPERATOR_PERMIT_EXP>
<SUBJECT_OBSERVED_20_MINUTES>YES</SUBJECT_OBSERVED_20
_MINUTES>
<TEST_20_MINUTES_PAST_ARREST>YES</TEST_20
_MINUTES_PAST_ARREST>
<REFUSAL_MIRANDA_READ>YES</REFUSAL_MIRANDA_READ>
</INPUT_VALUES>
</TRACS_IMPORT>