

```

<?xml version="1.0" standalone="yes"?>
<TRACS_IMPORT>
  <ALCOTEST_VALUES>
    <SERIAL>ARAH-0044</SERIAL>
    <IP_ADRESS>10.81.197.30</IP_ADRESS>
    <DATE>07/29/2020</DATE>
    <TIME>07:09PM</TIME>
  </ALCOTEST_VALUES>
  <CALCHECK_1>
    <CAL_MESSUNG_2_MESSUNG_ERROR>0</CAL_MESSUNG_2_MESSUNG_ERROR>
    <CAL_MESSUNG_2_IR_AAK_NULLWERT_1>0.00</CAL_MESSUNG_2
_IR_AAK_NULLWERT_1>
    <CAL_MESSUNG_2_IR_AAK_MESSWERT>0.10</CAL_MESSUNG_2
_IR_AAK_MESSWERT>
    <CAL_MESSUNG_2_EC_AAK_MESSWERT>0.09</CAL_MESSUNG_2
_EC_AAK_MESSWERT>
    <CAL_MESSUNG_2_IR_AAK_NULLWERT_2>0.00</CAL_MESSUNG_2
_IR_AAK_NULLWERT_2>
    <ID_BLANK_TIME_BEFORE_2>07:00:51PM
07/29/2020</ID_BLANK_TIME_BEFORE_2>
    <ID_TIME_START_BLOW_2>--:--:-- --/--/-----
</ID_TIME_START_BLOW_2>
    <ID_TIME_MEAS_2>07:01:28PM 07/29/2020</ID_TIME_MEAS_2>
    <ID_BLANK_TIME_AFTER_2>07:02:05PM
07/29/2020</ID_BLANK_TIME_AFTER_2>
  </CALCHECK_1>
  <SUBJECT_TEST>
    <PROB_MESSUNG_2_MESSUNG_ERROR>0</PROB_MESSUNG_2
_MESSUNG_ERROR>
    <PROB_MESSUNG_2_IR_AAK_NULLWERT_1>0.00</PROB_MESSUNG_2
_IR_AAK_NULLWERT_1>
    <PROB_MESSUNG_2_IR_AAK_MESSWERT>0.00</PROB_MESSUNG_2
_IR_AAK_MESSWERT>
    <PROB_MESSUNG_2_EC_AAK_MESSWERT>0.00</PROB_MESSUNG_2
_EC_AAK_MESSWERT>
    <PROB_MESSUNG_2_IR_AAK_NULLWERT_2>0.00</PROB_MESSUNG_2
_IR_AAK_NULLWERT_2>
    <PROB_MESSUNG_2_BLAS_FEHLVERSUCHE>1</PROB_MESSUNG_2
_BLAS_FEHLVERSUCHE>
    <PROB_MESSUNG_2_BLAS_VOLUMEN>2.1</PROB_MESSUNG_2
_BLAS_VOLUMEN>
    <PROB_MESSUNG_2_BLAS_ZEIT>16.6</PROB_MESSUNG_2_BLAS_ZEIT>
    <ID_BLANK_TIME_BEFORE_3>07:05:02PM 07/29/2020,07:03:13PM
07/29/2020</ID_BLANK_TIME_BEFORE_3>
    <ID_TIME_START_BLOW_3>07:05:25PM
07/29/2020</ID_TIME_START_BLOW_3>
    <ID_TIME_END_BLOW_3>07:05:42PM 07/29/2020</ID_TIME_END_BLOW_
3>
    <ID_TIME_MEAS_3>07:05:50PM 07/29/2020,07:04:15PM
07/29/2020</ID_TIME_MEAS_3>
    <ID_BLANK_TIME_AFTER_3>07:06:40PM
07/29/2020</ID_BLANK_TIME_AFTER_3>

```

```

</SUBJECT_TEST>
<CALCHECK_2>
  <CAL_MESSUNG_3_MESSUNG_ERROR>0</CAL_MESSUNG_3_MESSUNG_ERROR>
  <CAL_MESSUNG_3_IR_AAK_NULLWERT_1>0.00</CAL_MESSUNG_3
_IR_AAK_NULLWERT_1>
  <CAL_MESSUNG_3_IR_AAK_MESSWERT>0.10</CAL_MESSUNG_3
_IR_AAK_MESSWERT>
  <CAL_MESSUNG_3_EC_AAK_MESSWERT>0.09</CAL_MESSUNG_3
_EC_AAK_MESSWERT>
  <CAL_MESSUNG_3_IR_AAK_NULLWERT_2>0.00</CAL_MESSUNG_3
_IR_AAK_NULLWERT_2>
  <ID_BLANK_TIME_BEFORE_4>07:06:40PM
07/29/2020</ID_BLANK_TIME_BEFORE_4>
  <ID_TIME_START_BLOW_4>--:--:-- --/--/-----
</ID_TIME_START_BLOW_4>
  <ID_TIME_MEAS_4>07:06:42PM 07/29/2020</ID_TIME_MEAS_4>
  <ID_BLANK_TIME_AFTER_4>07:07:18PM
07/29/2020</ID_BLANK_TIME_AFTER_4>
</CALCHECK_2>
<GENERAL_DATA>
  <ID_SERIAL_NO>ARAH-0044</ID_SERIAL_NO>
  <ID_SW_VERSION> 8321288 1.12.2</ID_SW_VERSION>
  <ID_START_TIME>06:53:38PM 07/29/2020</ID_START_TIME>
  <ID_END_TIME>07:08:12PM 07/29/2020</ID_END_TIME>
  <ID_LAST_CAL_DATE>08/20/2019</ID_LAST_CAL_DATE>
  <ID_AAK_ENDRESULT> 0.00 %BAC</ID_AAK_ENDRESULT>
  <ID_TEST_COUNTER>500</ID_TEST_COUNTER>
  <ID_MEAS_PROC>1</ID_MEAS_PROC>
  <ID_CALIBRATION_COUNTER>92</ID_CALIBRATION_COUNTER>
  <ID_ERROR_PROTOKOLL>0</ID_ERROR_PROTOKOLL>
  <ID_TEST_GAS_TYPE>2</ID_TEST_GAS_TYPE>
  <ID_TEST_GAS_INLET>1</ID_TEST_GAS_INLET>
  <ID_TEST_GAS_CONC>25.00</ID_TEST_GAS_CONC>
  <ID_TEST_CFG_SENSOR>0</ID_TEST_CFG_SENSOR>
  <ID_DATA_INPUT_ON_OFF>1</ID_DATA_INPUT_ON_OFF>
  <ID_IR_AVERAGE>25251</ID_IR_AVERAGE>
  <ID_EC_SENSOR_OFFSET>113</ID_EC_SENSOR_OFFSET>
  <ID_HOSE_TEMP>47.1</ID_HOSE_TEMP>
  <ID_IR_SENSOR_TEMP>45.3</ID_IR_SENSOR_TEMP>
  <ID_INTERNAL_DEVICE_TEMP>37.1</ID_INTERNAL_DEVICE_TEMP>
  <ID_12V_VOLTAGE>12.2</ID_12V_VOLTAGE>
  <ID_3V_BACKUP_VOLTAGE>3.3</ID_3V_BACKUP_VOLTAGE>
  <ID_MS_SW_CRC>0x6581</ID_MS_SW_CRC>
  <ID_PRESSURE_DRY_GAS>0</ID_PRESSURE_DRY_GAS>
  <ID_DRY_GAS_LOT_NO>1057590</ID_DRY_GAS_LOT_NO>
  <ID_DRY_GAS_EXP_DATA>12/08/2021</ID_DRY_GAS_EXP_DATA>
</GENERAL_DATA>
<INPUT_VALUES>
  <UF_CASE_NUMBER>SY20-0901</UF_CASE_NUMBER>
  <ZERO_TOLERANCE_CASE>NO</ZERO_TOLERANCE_CASE>
  <TROOP>T</TROOP>
  <STATION>SCHUYLER</STATION>

```

<ARREST\_DATE>07/29/2020</ARREST\_DATE>  
<ARREST\_TIME>06:39PM</ARREST\_TIME>  
<ARRESTING\_MEM\_LAST>DEMBROW</ARRESTING\_MEM\_LAST>  
<ARRESTING\_MEM\_FIRST>ADAM</ARRESTING\_MEM\_FIRST>  
<ARRESTING\_MEM\_MI>M</ARRESTING\_MEM\_MI>  
<ARRESTING\_MEM\_SHIELD>745</ARRESTING\_MEM\_SHIELD>  
<SUBJECT\_LAST\_NAME>MARTINO</SUBJECT\_LAST\_NAME>  
<SUBJECT\_FIRST\_NAME>ROSEMARY</SUBJECT\_FIRST\_NAME>  
<SUBJECT\_MI>--</SUBJECT\_MI>  
<SUBJECT\_DOB>06/13/1952</SUBJECT\_DOB>  
<SUBJECT\_AGE>68</SUBJECT\_AGE>  
<SUBJECT\_GENDER>FEMALE</SUBJECT\_GENDER>  
<OPERATOR\_LAST\_NAME>DEMBROW</OPERATOR\_LAST\_NAME>  
<OPERATOR\_FIRST\_NAME>ADAM</OPERATOR\_FIRST\_NAME>  
<OPERATOR\_MI>M</OPERATOR\_MI>  
<OPERATOR\_SHIELD\_NO>745</OPERATOR\_SHIELD\_NO>  
<OPERATOR\_PERMIT\_NO>43078</OPERATOR\_PERMIT\_NO>  
<OPERATOR\_PERMIT\_EXP>12/05/2020</OPERATOR\_PERMIT\_EXP>  
<SUBJECT\_OBSERVED\_20\_MINUTES>YES</SUBJECT\_OBSERVED\_20  
\_MINUTES>  
<TEST\_20\_MINUTES\_PAST\_ARREST>YES</TEST\_20  
\_MINUTES\_PAST\_ARREST>  
<REFUSAL\_MIRANDA\_READ>YES</REFUSAL\_MIRANDA\_READ>  
</INPUT\_VALUES>  
</TRACS\_IMPORT>