

New Hartford, NY

Existing Conditions Scan

Mixed Use Corridor Segment

Only Signalized Intersection

Competing Interests

Access to multiple sites

Only Sidewalk Segment

At-Grade Rail Crossing

Limited Access 4-Lane Highway

Major Intersection

Unsignalized Intersection

Culvert Restriction & Full Ingress/Egress

Right-Out Only Exit

Route 8 Underpass

No pedestrian infrastructure at the crossing

Ramps create crossing impediment

Very wide intersection

Significant intersection

Drains Hannaford Plaza

Provides an exit between signal and RR Tracks

Wide shoulders but no other non-auto infrastructure

Likely very rarely used

