

```

<?xml version="1.0" standalone="yes"?>
<TRACS_IMPORT>
  <ALCOTEST_VALUES>
    <SERIAL>ARAE-0022</SERIAL>
    <IP_ADRESS>10.81.193.44</IP_ADRESS>
    <DATE>09/19/2020</DATE>
    <TIME>06:46PM</TIME>
  </ALCOTEST_VALUES>
  <CALCHECK_1>
    <CAL_MESSUNG_2_MESSUNG_ERROR>0</CAL_MESSUNG_2_MESSUNG_ERROR>
    <CAL_MESSUNG_2_IR_AAK_NULLWERT_1>0.00</CAL_MESSUNG_2
_IR_AAK_NULLWERT_1>
    <CAL_MESSUNG_2_IR_AAK_MESSWERT>0.09</CAL_MESSUNG_2
_IR_AAK_MESSWERT>
    <CAL_MESSUNG_2_EC_AAK_MESSWERT>0.09</CAL_MESSUNG_2
_EC_AAK_MESSWERT>
    <CAL_MESSUNG_2_IR_AAK_NULLWERT_2>0.00</CAL_MESSUNG_2
_IR_AAK_NULLWERT_2>
    <ID_BLANK_TIME_BEFORE_2>06:31:56PM
09/19/2020</ID_BLANK_TIME_BEFORE_2>
    <ID_TIME_START_BLOW_2>--:--:-- --/--/-----
</ID_TIME_START_BLOW_2>
    <ID_TIME_MEAS_2>06:32:33PM 09/19/2020</ID_TIME_MEAS_2>
    <ID_BLANK_TIME_AFTER_2>06:33:02PM
09/19/2020</ID_BLANK_TIME_AFTER_2>
  </CALCHECK_1>
  <SUBJECT_TEST>
    <PROB_MESSUNG_2_MESSUNG_ERROR>1</PROB_MESSUNG_2
_MESSUNG_ERROR>
    <PROB_MESSUNG_2_IR_AAK_NULLWERT_1>--</PROB_MESSUNG_2
_IR_AAK_NULLWERT_1>
    <PROB_MESSUNG_2_IR_AAK_MESSWERT>--</PROB_MESSUNG_2
_IR_AAK_MESSWERT>
    <PROB_MESSUNG_2_EC_AAK_MESSWERT>--</PROB_MESSUNG_2
_EC_AAK_MESSWERT>
    <PROB_MESSUNG_2_IR_AAK_NULLWERT_2>--</PROB_MESSUNG_2
_IR_AAK_NULLWERT_2>
    <PROB_MESSUNG_2_BLAS_FEHLVERSUCHE>6</PROB_MESSUNG_2
_BLAS_FEHLVERSUCHE>
    <PROB_MESSUNG_2_BLAS_VOLUMEN>--</PROB_MESSUNG_2_BLAS_VOLUMEN>
    <PROB_MESSUNG_2_BLAS_ZEIT>--</PROB_MESSUNG_2_BLAS_ZEIT>
    <ID_BLANK_TIME_BEFORE_3>06:42:41PM 09/19/2020,06:34:10PM
09/19/2020,06:36:35PM 09/19/2020,06:38:19PM 09/19/2020,06:39:41PM
09/19/2020,06:41:05PM 09/19/2020,06:42:41PM
09/19/2020</ID_BLANK_TIME_BEFORE_3>
    <ID_TIME_START_BLOW_3>06:43:25PM 09/19/2020,06:35:26PM
09/19/2020,06:37:14PM 09/19/2020,06:38:36PM 09/19/2020,06:40:00PM
09/19/2020,06:41:36PM 09/19/2020,06:43:25PM
09/19/2020</ID_TIME_START_BLOW_3>
    <ID_TIME_END_BLOW_3>06:43:27PM 09/19/2020,06:35:29PM
09/19/2020,06:37:17PM 09/19/2020,06:38:39PM 09/19/2020,06:40:03PM
09/19/2020,06:41:38PM 09/19/2020,06:43:27PM

```

```

09/19/2020</ID_TIME_END_BLOW_3>
  <ID_TIME_MEAS_3>06:43:27PM 09/19/2020,06:35:39PM
09/19/2020,06:37:17PM 09/19/2020,06:38:40PM 09/19/2020,06:40:03PM
09/19/2020,06:41:39PM 09/19/2020,06:43:27PM
09/19/2020</ID_TIME_MEAS_3>
  <ID_BLANK_TIME_AFTER_3>--:--:-- --/--/-----
</ID_BLANK_TIME_AFTER_3>
  </SUBJECT_TEST>
  <CALCHECK_2>
    <CAL_MESSUNG_3_MESSUNG_ERROR>-</CAL_MESSUNG_3_MESSUNG_ERROR>
    <CAL_MESSUNG_3_IR_AAK_NULLWERT_1>-</CAL_MESSUNG_3
_IR_AAK_NULLWERT_1>
    <CAL_MESSUNG_3_IR_AAK_MESSWERT>-</CAL_MESSUNG_3
_IR_AAK_MESSWERT>
    <CAL_MESSUNG_3_EC_AAK_MESSWERT>-</CAL_MESSUNG_3
_EC_AAK_MESSWERT>
    <CAL_MESSUNG_3_IR_AAK_NULLWERT_2>-</CAL_MESSUNG_3
_IR_AAK_NULLWERT_2>
    <ID_BLANK_TIME_BEFORE_4>--:--:-- --/--/-----
</ID_BLANK_TIME_BEFORE_4>
  <ID_TIME_START_BLOW_4>--:--:-- --/--/-----
</ID_TIME_START_BLOW_4>
  <ID_TIME_MEAS_4>--:--:-- --/--/-----</ID_TIME_MEAS_4>
  <ID_BLANK_TIME_AFTER_4>--:--:-- --/--/-----
</ID_BLANK_TIME_AFTER_4>
  </CALCHECK_2>
  <GENERAL_DATA>
    <ID_SERIAL_NO>ARAE-0022</ID_SERIAL_NO>
    <ID_SW_VERSION> 8321288 1.12.2</ID_SW_VERSION>
    <ID_START_TIME>06:27:51PM 09/19/2020</ID_START_TIME>
    <ID_END_TIME>06:43:43PM 09/19/2020</ID_END_TIME>
    <ID_LAST_CAL_DATE>07/27/2020</ID_LAST_CAL_DATE>
    <ID_AAK_ENDRESULT>REFUSAL</ID_AAK_ENDRESULT>
    <ID_TEST_COUNTER>824</ID_TEST_COUNTER>
    <ID_MEAS_PROC>1</ID_MEAS_PROC>
    <ID_CALIBRATION_COUNTER>84</ID_CALIBRATION_COUNTER>
    <ID_ERROR_PROTOKOLL>46</ID_ERROR_PROTOKOLL>
    <ID_TEST_GAS_TYPE>2</ID_TEST_GAS_TYPE>
    <ID_TEST_GAS_INLET>1</ID_TEST_GAS_INLET>
    <ID_TEST_GAS_CONC>18.00</ID_TEST_GAS_CONC>
    <ID_TEST_CFG_SENSOR>0</ID_TEST_CFG_SENSOR>
    <ID_DATA_INPUT_ON_OFF>1</ID_DATA_INPUT_ON_OFF>
    <ID_IR_AVERAGE>21860</ID_IR_AVERAGE>
    <ID_EC_SENSOR_OFFSET>112</ID_EC_SENSOR_OFFSET>
    <ID_HOSE_TEMP>52.1</ID_HOSE_TEMP>
    <ID_IR_SENSOR_TEMP>45.5</ID_IR_SENSOR_TEMP>
    <ID_INTERNAL_DEVICE_TEMP>38.3</ID_INTERNAL_DEVICE_TEMP>
    <ID_12V_VOLTAGE>12.2</ID_12V_VOLTAGE>
    <ID_3V_BACKUP_VOLTAGE>3.3</ID_3V_BACKUP_VOLTAGE>
    <ID_MS_SW_CRC>0x6581</ID_MS_SW_CRC>
    <ID_PRESSURE_DRY_GAS>0</ID_PRESSURE_DRY_GAS>
    <ID_DRY_GAS_LOT_NO>1057590</ID_DRY_GAS_LOT_NO>

```

<ID_DRY_GAS_EXP_DATA>12/08/2021</ID_DRY_GAS_EXP_DATA>
</GENERAL_DATA>
<INPUT_VALUES>
<UF_CASE_NUMBER>SY20-1133</UF_CASE_NUMBER>
<ZERO_TOLERANCE_CASE>NO</ZERO_TOLERANCE_CASE>
<TROOP>T</TROOP>
<STATION>SYRACUSE</STATION>
<ARREST_DATE>09/19/2020</ARREST_DATE>
<ARREST_TIME>05:20PM</ARREST_TIME>
<ARRESTING_MEM_LAST>RODMAN</ARRESTING_MEM_LAST>
<ARRESTING_MEM_FIRST>CHAD</ARRESTING_MEM_FIRST>
<ARRESTING_MEM_MI>S</ARRESTING_MEM_MI>
<ARRESTING_MEM_SHIELD>3819</ARRESTING_MEM_SHIELD>
<SUBJECT_LAST_NAME>COOK GONZALEZ</SUBJECT_LAST_NAME>
<SUBJECT_FIRST_NAME>DONNA</SUBJECT_FIRST_NAME>
<SUBJECT_MI>P</SUBJECT_MI>
<SUBJECT_DOB>10/30/1976</SUBJECT_DOB>
<SUBJECT_AGE>43</SUBJECT_AGE>
<SUBJECT_GENDER>FEMALE</SUBJECT_GENDER>
<OPERATOR_LAST_NAME>LEONE</OPERATOR_LAST_NAME>
<OPERATOR_FIRST_NAME>GRAIG</OPERATOR_FIRST_NAME>
<OPERATOR_MI>G</OPERATOR_MI>
<OPERATOR_SHIELD_NO>2218</OPERATOR_SHIELD_NO>
<OPERATOR_PERMIT_NO>42832</OPERATOR_PERMIT_NO>
<OPERATOR_PERMIT_EXP>12/15/2021</OPERATOR_PERMIT_EXP>
<SUBJECT_OBSERVED_20_MINUTES>YES</SUBJECT_OBSERVED_20
_MINUTES>
<TEST_20_MINUTES_PAST_ARREST>YES</TEST_20
_MINUTES_PAST_ARREST>
<REFUSAL_MIRANDA_READ>YES</REFUSAL_MIRANDA_READ>
</INPUT_VALUES>
</TRACS_IMPORT>